



YOUR ISSE

CASE STUDY



THE CHALLENGE

- Frequent and severe damage to equipment, especially in injection systems
- Diesel with very high levels of contaminant particles
- Increased maintenance and repair costs
- **Extreme environmental working conditions**

THE SOLUTION



Filters installed at the fuel receiving point and on mobile dispensing tankers in the field.

RESULT: Ultra clean and dry diesel – ISO 4406: 10/9/7





"In my area, I can highlight that the maintenance department, which previously reported a high rate of repairs, now practically reports no failures, especially in the injection systems. This remarkable improvement is attributed to FMS filtration."

Engr. José Carlos Lechuga, Coordinator of Warehouses, Supply, and Contracts. Book a meeting to discover how to effectively

PROTECT YOUR ASSETS

